

Sling Aircraft (Pty) Ltd Registration no 2002/022837/07

Approved Maintenance Organisation AMO1264 Manufacturing Organisation M677

Hangar 8 Tedderfield Airpark Nettleton Road Eikenhof Johannesburg 1872 South Africa PO Box 308 Eikenhof Johannesburg 1872 South Africa [T]+27 (0) 11 948 9898 [F]+27 (0) 86 632 4493 sales@slingaircraft.com www.slingaircraft.com

SERVICE BULLETIN

#0004 Revision 1

Page 1 of 4

(Sling Aircraft (Pty) Ltd. considers compliance with all Service Bulletins mandatory)

NOTE – THIS SERVICE BULLETIN REPLACES SERVICE BULLETIN #0004 (REVISION 0) IN ITS ENTIRETY SERVICE BULLETIN #0004 (REVISION 0) IS ACCORDINGLY CANCELLED WITH EFFECT FROM 19/09/2025

RELEASE DATE: 19/08/2025

REASON FOR REVISION 1: Update to list of affected models

EFFECTIVE DATE: 19/08/2015

SUBJECT: Placement of the ELT antenna

MODELS AFFECTED: All Sling LSA, Sling 2, Sling 2 Taildragger & Sling 4 aircraft where

an ACK E-04 ELT is installed prior to 19/08/2015.

(Aircraft produced after 14/07/2020 will have an ARTEX 345 ELT

and are NOT affected by this Service Bulletin).

COMPLIANCE TIME: Next MPI (Mandatory Periodic Inspection)

1. DESCRIPTION AND PURPOSE:

To ensure the correct placement of the ELT antenna.

2. MATERIAL INFORMATION:

2.1. PARTS AND CONSUMABLES LIST:

- a) 1 x ELT Antenna Bracket (CF-ANG-052-X-C-0)
- b) 2 x 3.2 x 8mm Aluminium Rivets

2.2. TOOLS REQUIRED:

- a) 1 x 3.3mm Drill Bit
- b) 1 x Drill
- c) 1x Cleco
- d) 1 x Cleco Pliers
- e) 1x Rivet Gun

2.3. MATERIAL RESPONSIBILITY:

Sling Aircraft (Pty) Ltd will provide the required parts listed in Section 2.1 for all aircraft subject to the Service Bulletin.

DC-SBI-001-X-3.0	18 FEBRUARY 2020	Page 1 of 4

2.4. COMPANY SUPPORT INFORMATION

Sling Aircraft AMO 1264 (Johannesburg, South Africa) is available to perform the required work on all aircraft delivered to its premises. The aircraft may be flown to an aircraft maintenance organisation for the work to be carried out. Person(s) implementing the work are required to follow instructions set out below. Sling Aircraft cannot accept any responsibility for the quality of work performed in implementing this Service Bulletin, if the work is not performed by Sling Aircraft AMO 1264 (Johannesburg, South Africa).

All work carried out on the aircraft with respect to this Service Bulletin (Service Bulletin 0004) may be performed by the kit builder. Refer to the legal requirements of the governing aviation authority of the country where the actions, as detailed by this Service Bulletin, are to be carried out. Sling Aircraft will cover the installation costs of aircraft under warranty. Sling Aircraft is not responsible for costs related to shipping, downtime, loss of income, etc.

2.5. COMPANY SUPPORT INFORMATION

To request Service Bulletin kits, please use the following contact details: sales@slingaircraft.com, or contact your local distributer.

Make use of the following contact details for any related technical queries: airworthiness@slingaircraft.com or technical@slingaircraft.com.

3. INSTRUCTIONS:

If the **ACK E-04** ELT antenna is mounted in any place other than what is stipulated in this service bulletin, then this service bulletin will apply. The installation instructions in Figure 2 on the following page illustrate the correct installation.

Note: As of 14 July 2020, the **ACK E-04** ELT was replaced with the **ARTEX 345** ELT. The **ARTEX 345** ELT is mounted in a new location within the empennage fairing. This location is the preferred mounting position recommended by Sling Aircraft to ensure compliance with requirements for an externally mounted antenna. The two different ELT options are shown in Figure 1.





Figure 1

DC-SBI-001-X-3.0	18 FEBRUARY 2020	Page 2 of 4




Figure 2

Signed on this the 19th day of August 2025

ACCOUNTABLE MANAGER

MR JAMES PITMAN