



THE AIRPLANE FACTORY (Pty) Ltd
Registration no 2002/022837/07
Approved Maintenance Organisation AMO1264
Manufacturing Organisation M677

Hangar 8 Tedderfield Airpark
Nettleton Road Eikenhof
Johannesburg 1872
South Africa

PO Box 308
Eikenhof
Johannesburg 1872
South Africa

[T]+27 (0) 11 948 9898
[F]+27 (0) 86 632 4493
sales@airplanefactory.co.za
www.airplanefactory.co.za

SAFETY ALERTS

#0011

Page 1 of 2

(The Airplane Factory (Pty) Ltd. considers compliance with all Safety Alerts mandatory)

RELEASE DATE: 14/10/2019

EFFECTIVE DATE: 14/10/2019

SUBJECT: Replacement of fuel pump assembly for aircraft fitted with 915 iS and 912 iS engines

MODELS AFFECTED: Sling aircraft fitted with Rotax® 915 iS and 912 iS engines operating with the Rotax® accessory fuel pump assembly with part and serial numbers stated in the attached Rotax® Alert Service Bulletin ASB-915 i A-008 / ASB-912 i-011

COMPLIANCE TIME: Before the next flight

LABOUR TIME: Refer to the attached Rotax® Alert Service Bulletin ASB-915 i A-008 / ASB-912 i-011

DESCRIPTION AND PURPOSE:

The Safety Alert serves to inform customers of the service bulletin published by Rotax® regarding the replacement of the fuel pump assembly for 915 iS and 912 iS engines.

PARTS AND CONSUMABLES LIST:

Refer to the attached Rotax® Alert Service Bulletin ASB-915 i A-008 / ASB-912 i-011.

TOOLS REQUIRED:

Refer to the attached Rotax® Alert Service Bulletin ASB-915 i A-008 / ASB-912 i-011.

INSTRUCTIONS:

Refer to the attached Rotax® Alert Service Bulletin ASB-915 i A-008 / ASB-912 i-011.

Signed on this the 14th day of October..... 2019



ACCOUNTABLE MANAGER
MR ANDREW PITMAN